

## 3D METAL MODEL



3D-S016








Insert tab and bend 90 degrees for most visible areas



Insert tab and twist 90 degrees is best in some areas to ensure a tight connection





1

In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

## Assembly Flow Chart

